

FIG. 1




FIG. 2





FIG. 3




*FIG. 4*

52                      53                      51                      54

INSPECTION ITEM NAME	REAGENT MANUFACTURER NAME	ITEM CODE
ITEM 1	COMPANY A	A1001
ITEM 2	COMPANY B	B2002
ITEM 3	COMPANY A	A1003
ITEM 4	COMPANY B	B2005
ITEM 5	COMPANY C	C3007
ITEM 6	COMPANY C	C3008


T06280" E6504660

FIG. 5



TIME

FIG. 6



TIME